Metzger © O Autoteile

New at METZGER:


Oil stop cable for connecting lead camshaft adjuster Mercedes Benz: A 271 150 27 33

Innovation:

Oil stop line connector Oil indicator stranded wire



The loss of oil at the camshaft adjuster is a known problem with certain Mercedes-Benz engines. Due to the capillary effect, the oil in the wiring harness can reach the control unit. This can lead to failure of the electronics. The Metzger's "oil stop cable" effectively prevents oil from penetrating the wiring harness.



Werner Metzger GmbH Rita-Maiburg-Str. 33 D-70794 Filderstadt

phone +49 711 / 160 86 - 21 fax +49 711 / 160 86 - 86

Part number 2324048

E-mail export@werner-metzger.com www.werner-metzger.com